
DUROMETER CONVERSION TABLE

The hardness values listed below are approximate and should only be used as a durometer selection guide.

HARDNESS VALUE					
A	B	C	D	O	OO
100	85	77	58		
95	81	70	46		
90	76	59	39		
85	71	52	33		
80	66	47	29	84	96
75	62	42	25	79	97
70	56	37	22	75	95
65	51	32	19	72	94
60	47	28	16	69	93
55	42	24	14	65	91
50	37	20	12	61	90
45	32	17	10	57	88
40	27	14	8	53	86
35	22	12	74	8	83
30	17	9	6	42	80
25	12			35	76
20	6			28	70
15				21	62
10				14	55
5				8	45

Precision Technologies, Inc.
1931 Allegheny Blvd, Box 351
Reno PA 16343
Phone: 814-676-3502
Fax: 814-676-3530
Email: precision@ptiprototype.com